

August 1958

INDEX

to

ISSUE No. 7
(Please destroy
previous Issue)

IMPROVEMENTS AND ALTERATIONS

This Index embodies all information issued **up to and including** Service Memorandum No. MG/224 and Parts List Amendment No. PMG/285. Workshop Manual references, where applicable, are shown in italics and may include any additional or amended sheet issued to date.

Figures in heavy type denote that the change is embodied in the current Parts List (Part No. AKD599).

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
GENERAL			Crankshaft		
Coupé model—introduction ..		129, 130	—bearings — main — single lubrication hole		104
			—oil return thread—diameter reduced to improve design ..	184 (A20)	
			Cylinder block		
			—drain tap modified to improve block drainage ..		259
POWER UNIT			—front cover—modified to suit new timing chain tensioner ..		51
Camshaft			—modified to suit new timing chain tensioner		51
—gear and locating plate—modified to suit new timing chain tensioner		51	—rear main bearing oil leaks—Service rectification	212	
—larger lock washer—to increase 'life'		246	—side cover and vent pipe modified to increase clearance between vent pipe and exhaust manifold		271
Carburettor			Cylinder head		
—distance piece made from harder material to prevent breaking up and carburettor flange fractures		268	—bracket — rocker shaft — improved design		96
—needle and seat assembly—modified type		134	—gasket—copper and asbestos replaces copper, steel, and asbestos type	205	247
Clutch			—gasket—copper ferrules fitted to improve sealing	206	
—pressure plate — stronger springs to reduce slip when changing gear at high engine speeds	205	247	—guide—exhaust valve—length shortened		101
—withdrawal lever bolt—larger diameter and abutment for locknut to prevent over-tightening and stripped threads		106	—guide—inlet valve—bore increased		265
—withdrawal lever bolt modified—lever, bush, and gearbox front cover modified to suit	(E8)	101	—heater outlet—diameter increased—to reduce restriction in flow from head to heater outlet pipe	198	

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
Power Unit—continued			Gearbox—continued		
Cylinder head—continued			—fork locating screws — improved accessibility	170	64
—inlet ports—modified to improve design		246	—front cover—oil leaks—prevention in service	183	
—push-rod with larger diameter end and tappet with ball seat modified to suit—improved design		102	—front cover—oil seal fitted between front cover and first motion shaft to improve oil sealing	190 (F6)	113
—valve—inlet—modified to suit larger diameter guide ..		265	—front cover—to suit larger-diameter clutch withdrawal bolt		101, 106
Distributor			—layshaft—alternative ..		95
—cable—run modified ..		90, 132	—mounting plate—diameter of crankshaft clearance hole reduced to improve design ..	184	
—fitted with pre-tilted contact breaker	(B8)	90, 132	—mounting plate—oil escape recess and groove in front face to prevent oil leakage into clutch housing	177 (A20)	
—head—fuel entry prevented by fuel trap in ignition control pipe	186 (B9)	111	—oil baffle fitted to first motion shaft to improve oil sealing ..		89
Dynamo			—second speed synchronizer—width of slots in front face reduced to facilitate engagement of third gear	205	
—modified to eliminate need for commutator cover ..	(N16)	93	—selector—first, second, third, fourth, and reverse—bosses lengthened to provide overshoot stops	170	64
—pulley—diameter reduced to increase dynamo speed ..	205	244	—shaft—first, second, third, fourth, and reverse forks—vented at front end to improve gear change		94
Engine mounting plate			—shaft—third, fourth, and reverse forks—conical holes repositioned to improve accessibility of fork locating screws	170	64
—front modified to suit new timing chain tensioner ..		51	—speedometer pinion—nylon type to ensure quieter running		246
Fan					
—belt—shorter type to suit smaller-diameter dynamo pulley	205	244			
Gearbox					
—extension — oil seal — alternative—deleted to improve oil sealing		87			
—extension—oil seal—synthetic rubber type replaces leather to improve oil sealing ..	210	261			
—fork—first, second, third, fourth, and reverse—lugs deleted and locating block width increased to improve accessibility of locating screws	170	64			
—fork—third and fourth gears —improved design		269			

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
Power Unit—continued			TRANSMISSION AND REAR AXLE		
Oil filter			Propeller shaft		
—modified to permit use of Purolator or Tecalemit type	(A20)	266, 270	—shaft and dust cover—modified to suit revised splines on gearbox tail shaft		222
Pistons			Rear axle		
—grades and oversizes for service	194		—alternative—rear axle complete (9-41 ratio) (wire wheels)		92
—grooves deepened to suit thick rings	224	282	—case—left-hand end threaded L/H. Bearing locknuts and washers altered to suit to improve design (disc wheel type only)	173 (H11)	87
—gudgeon pin hole diameter reduced to strengthen pin ..	(A20)	275	—case—R/H and L/H threads for hub bearing nuts—locknut and tab washers modified to suit (wire wheel type only)	176 (H11)	92
—rings—radial thickness increased to improve oil consumption	224	282	—hub—oil seals fitted to improve sealing	(H11)	111, 113
—top rings chromium-plated to reduce oil consumption and increase life of rings ..	182 (A20)	104			
Push-rods			SUSPENSION, STEERING, ROAD SPRINGS AND WHEELS, SHOCK ABSORBERS, AND BRAKES		
—end diameter increased to improve design	182 (A20)	104	Brakes		
Tappets			—bleeder screws—importance of checking tightness ..	193	
—modified to suit new push-rods	182 (A20)	104	—master cylinder—deeper filler cap to give more thread engagement		267
Thermostat			—UNF threads standardized		246
—modified type requiring no joint washer		262	—wheel cylinders (rear)—90° banjo replaces straight type—improved design	198	222
Timing chain tensioner			Front suspension		
—rubber slipper plate type introduced	(A18)	51	—coil springs—free length reduced to improve road-holding	182 (K9)	103, 105
Vacuum ignition control pipe			—upper links modified to improve design		240
—modified to suit new carburettor union		222			
Valve rocker cover					
—joint—thicker to improve oil sealing	205	247			
Water outlet elbow					
—material improved to prevent corrosion by anti-freeze	184				
Water pump and fan					
—plug—body—oil filler—improved accessibility with longer and hexagonal head ..	175	91			
—redesigned to reduce number of separate components ..		278			

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
Suspension, Steering, Road Springs and Wheels, Shock Absorbers, and Brakes —continued			Hood and side curtains—continued		
Road wheels			—canopy—stitching—sealing ..	196 (S10)	107
—redesigned hub-cap introduced (wire type)		265	—frame—modified		100
—shape of centre disc modified to improve resistance to crack development	218		—side-curtains—modified ..		
Shock absorbers			Instruments		
—rear-time settings reduced to improve ride	218		—re-styled		102, 103
			—thermometer pipe clips repositioned to improve pipe layout		273, 274
			Sill finishers		
			—introduced to improve appearance	190	113
			Sliding windows (optional extras)		
			—aluminium frames introduced to improve design		264
			Windscreen		
			—stanchion bolt sealing ..	189	
			Windscreen washer (optional extra)		
			—fixed jets supplied		263
CHASSIS, BODY, RADIATOR, PETROL, AND EXHAUST SYSTEMS			ELECTRICAL EQUIPMENT		
Accelerator			Cigar lighter		
—cable—auxiliary return spring fitted	202 (D13)	239	—optional extra		258
—cable—fitting auxiliary return spring (Service)	197		Distributor		
Coupé			—fitted with pre-tilted contact breaker	(B8)	90
—introduction		129, 130	—cable—run modified ..		90
Doors			—head—fuel entry prevented by fuel trap in ignition control pipe	186	111
—insufficient opening—service remedy and production improvement (coupé)	221	285	Dynamo		
—lock cables—improved method of attachment to lever	219		—modified to eliminate need for commutator cover ..	(N17)	93
—locking handle fitted to driver's side	202	239	—pulley—diameter reduced to increase dynamo speed ..	205	244
Hardtop			Ignition coil		
—optional extra		107, 110	—steady plate to suit modified dynamo		95
Heater			Vacuum ignition control		
—noisy operation—prevention	203		—pipe—fuel trap incorporated to prevent fuel entering distributor head	186 (B9)	111
Hood and side-curtains					
—backlight—replacement method for Vybak panel ..	216				
—canopy—quarter-light Vybak panels introduced to improve rear vision	190	113			

SUBJECT	Information issued under		SUBJECT	Information issued under	
	Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/		Service Memorandum No. and Workshop Manual Sheet No.	Parts List Amendment No. PMG/
<p>Electrical Equipment—contd. Windscreen wiper —9½ in. arm with 8 in. blade to improve windscreen wiping</p> <p>LITERATURE List of Suggested Stock Holdings. Maintenance Service Voucher Booklet (Part No. AKD727). Operation Manual (First Edition)—Part No. AKD598. Operation Manual (Fourth Edition) for Cars after No. 20671—Part No. AKD598D. Operation Manual for Twin Cam model (First Edition)—Part No. AKD879. Parts List (Part No. AKD599): Additional Pages 154 to 187. 'Insert' for Twin Cam model (Part No. AKD599A). Parts List Amendments Nos. PMG/105 to 107, 111 to 113, 115 to 118, 129 to 231, 235, 237 to 240, 244, 246, 247, 258 to 276, 278 to 282, 284 and 285. Price List (April 1957)—Part No. AKD693. Supplements Nos. 1 to 14. Schedule of Repair Charges (U.K. only)—Part No. AKD873. Schedule of Repair Times—Part No. AKD782. Service Parts Pack—Initial List. Service Tool Catalogue Part No. AKD659. The following have been issued for the above catalogue: Amended Sheets—Issue No. 2—iii and iv.</p>		95, 101	<p>Literature—continued Workshop Manual—Part No. AKD600. The following have been issued for the above Manual: Additional Sheets—Q.7 to Q.14; S.9, S.10. Amended Sheets—Issue No. 2—1, 2; A.5, A.6, A.13 to A.16; B.3, B.4, B.7, B.8; C.3, C.4; D.15; E.1, E.2, E.7, E.8; F.1, F.2; G.3; H.5, H.6, H.9, H.10; J.1 to J.6; K.9; M.11, M.12; N.1, N.2, N.5, N.6, N.9 to N.12; O.3, O.4; Q.1 to Q.4; S.3 to S.6; Lubrication Chart. Amended Sheets—Issue No. 3—B.1, B.2, B.9; C.5 to C.7; D.1, D.2, D.7, D.8, D.13, D.14; F.5, F.6; H.7, H.8; K.1 to K.4; M.7, M.8; N.17; P.3 to P.6; Q.5, Q.6; S.1, S.2. Amended Sheets—Issue No. 4—3, 4, 15 to 20; A.9 to A.12; H.1, H.2; S.7, S.8. Amended Sheets—Issue No. 5—21; A.3, A.4, A.17, A.18; H.11, H.12; P.1, P.2; Key to Recommended Lubricants. Amended Sheets—Issue No. 6—5 to 10; A.1, A.2, A.7, A.8. Amended Sheets—Issue No. 8—A.19, A.20.</p>		