

CONFIDENTIAL

| |
|--------------------------------------|
| Distributor & Dealer Organization |
| No. MG / 310 |
| Fleet Users |
| No. |
| 30 March 1960 |

SERVICE MEMORANDUM

VALVE SPRINGS

MGA TWIN-CAM

As from Engine No. 2251, stronger valve springs, Part Nos. AEH668 (outer) and AEH669 (inner), were fitted in production.

If valve crash is experienced below the normal maximum revolutions of the engine (7,000 R.P.M.), a complete set of the stronger springs should be fitted.