CONFIDENTIAL



SERVICE MEMORANDUM

MGF/34

25 November 1959

DISC BRAKE PADS

"MGA" 1600

An improved type of disc-brake pad was introduced at Car No. 78106 (disc-wheels) and Car No. 78114 (wire-wheels). The new pads are available in sets - readily identifiable by a red mark - to Part No. 8G8379, and only pads to this part number will be available in service.

It is essential that, if the improved pads are fitted to earlier cars, both right-hand and left-hand brakes must be equipped.

Caliper unit assemblies fitted with the improved pads have been allocated new part numbers - BTB166 (R/H) and BTB167 (I/H). If these are fitted singly prior to the Car Nos. given in the first paragraph, the pads in the opposite caliper unit must be replaced by the later type.