SERVICE MEMORANDUM

6 Jan. 1960

IMPORTANT MODIFICATIONS

Parts List
Amendment No

Hood

From Car No. 78249 - 'MGA 1600'
2540 - 'MGA' Twin-Cam

PMG/405 PMG/410

To improve sidescreen stowage and allow full seat adjustment

Hood linkage modified to enable hood to be folded up under rear tonneau panel, permitting sidescreens to be stowed on top of battery cover panel instead of in front of it as previously.

Interchangeable.

Rod engine
oil level
indicator

From Engine No. 16GA-U-H-9649 - 'MGA 1600'

PMG/413

To improve accessibility

Oil level indicator now cranked away

from crankcase.

Interchangeable.