

**CONFIDENTIAL**

MG / 329

# **SERVICE MEMORANDUM**

29 Sept. 1960

WINDSCREEN CONTAMINATION

ALL MODELS

If windscreen smearing has occurred, due to the indiscriminate use of a duster containing a silicone-based polish (or traces of this type of polish washed down from the roof) either of the following methods may be employed for removal:

- (a) an extremely mild abrasive such as used for domestic purposes,
- (b) a very strong solution of detergent and hot water.