

STANDARD ENGINE
LOCKTAB WASHER

$\varnothing 1.860$
 $\varnothing 0.875$
THRU

IF THERE IS
A KEY NOTCH
HERE YOU CAN
IGNORE IT

0.038

MAKE (2) NARROW
SAW CUTS

0.16

0.22

BEND TAB DOWN

IF TAB LENGTH IS
TOO LONG FOR
DEPTH OF HOLE
IN PULLEY,
THEN TRIM TAB
TO SUIT.

0.20
REF

0.73

1.66 REF

